

Fig. 1




Fig. 2




Fig. 3




Fig. 4






Fig. 6

66c



66d




Fig. 7

66e

42a

42b

42c

42d

66e

networkcar

Text Messaging

Service Records

Mapping

Diagnostics

Found 12 service record(s). Click the Invoice Date or Work Order

| Invoice Date | Work Order # | Company |
|--------------|--------------|-----------------------------|
| 11/10/03 | 209729 | Honda of El Cerrito Service |
| 08/22/03 | 202481 | Honda of El Cerrito Service |
| 08/21/03 | 199734 | Honda of El Cerrito Service |
| 03/15/03 | 189065 | Honda of El Cerrito Service |
| 02/03/03 | 185346 | Honda of El Cerrito Service |
| 11/06/02 | 177232 | Honda of El Cerrito Service |
| 09/08/02 | 171184 | Honda of El Cerrito Service |
| 07/09/02 | 165170 | Honda of El Cerrito Service |
| 06/17/02 | 161760 | Honda of El Cerrito Service |
| 04/30/02 | 158293 | Honda of El Cerrito Service |
| 03/28/02 | 155340 | Honda of El Cerrito Service |
| 03/22/02 | 154370 | Honda of El Cerrito Service |

164

Service Record

209729

11/09/03

PAUL FORTE (19)

38143

386.07

Job Information

Job Pay Type

Operation

Technician ID

33

1 Customer 01HQZ-37500 - 37500 MILE SERVICE

Comments: CUSTOMER REQUESTS 37 500 MILE SERVICE ESTIMATE INCLUDES HAZARDOUS WASTE CHARGE; RECOMMENDED MAINTENANCE ; PERFORMED 37 500 MILE SERVICE

33 Customer 30HQZ-FRZPORTR - FRONT PADS/ROTORS

Comments: NEEDS FRONT BRAKES; DUE TO NORMAL WEAR; REPLACED FRONT BRAKE PADS AND RESURFACED BOTH FRONT ROTORS

168

Fig. 8